Work Orde Thursday, Septen	er ID 62264 nber 23, 2010 3:01:41 PM				4	SH	18	FR	IDAY	Page 1
Revision ID:	D120-639-011		Accept					Setup Star		
	Tungsten Carbide Wearplate 9/24/2010			Cust Item I Customer:	D:			310	P 	
Approvals:	Process Plan: MC	Date: 10-9-2	Pooling:	Da	nte:			Run Sta	rt	
	QC:	Date:	SPC (Y/N):		ite:			Sto	р	
Sequence ID/ Work Center II	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accep: Qty	t Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr									
DSI 9223	Rev A									
IIN-D120-639	Rev A									
100 DC	DOCUMENT CONTRO	L	0.00						-	
Document Control	Memo Photocopy I	luefile and type labels per		CHG 002 2 1d	01/24					

105

Pick Kit

0.00

Packaging

Memo

0.00

\$010/4/24 W

Packaging

W/O: WORK ORDER CHAN					NGES					
DATE	STEP	PRO	OCEDURE CH	ANGE	B	y 1	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									F100 Wgi	
Part No	•	PAR #:	Fault Cat	egory:	NCR: Y	es N	o DQ /	A:	Date:	
			Disposition: QA							
NCR:			WORK ORI	DER NON-CONFOR	MANCE (N	ICR)			••	
DATE	STEP	Description of NC Corrective Action			Section B	veri			Approval	Approval
	OIL.	Section A	Initial Chief Eng	Action Description Chief Eng		gn & Date	Section	on C	Chief Eng	QC Inspector
										,
								*		
					·	,	 		I	1
				· .		-				
						,				

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Work Order ID 62264

Thursday, September 23, 2010 3:01:41 PM



Page 2

Item ID:

D120-639-011

Accept

Setup Start

Stop



Revision ID:

Item Name:

Tungsten Carbide Wearplate

Start Date:

9/24/2010

Start Oty: 2.00

Rea'd Oty: 2.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: Date:

Tooling:

Date: Date:

Start Run



Required Date: 9/27/2010

QC: Date:

SPC (Y/N):

Set Up/

Tool ID

Tool # Plan

Code

Accept Qty

Reject Qty

Stop

Reject Number Stamp

Insp.

Sequence ID/ Work Center ID

110

QC

Quality Control

Operation Description

Packaging

QC4- 100% Inspect kits for completeness

Memo

Run Hours 8 10/02/24

120

Packaging

Packaging

Memo

0.00

0.00

Package and Identify as per PPP D120-639-011

130

OC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/09/24 48) NWP 10-9-24

W/O:			W	ORK ORDER CHANGE	S				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						ķ			
Part No: PAR #:		PAR #:	Fault Cat	egory:	NCR: Yes	No DQA	:	_ Date: _	
Resolution:			Dispositi	on:	QA: N/C Clo	sed:		Date: _	
NCR:		V	VORK ORE	DER NON-CONFORMA	NCE (NCR)				
DATE	STEP	Description of NC	Corrective Action Section Initial Action Description		n B Sign &		ification	Approval Chief Eng	Approval
	<u> </u>	Section A	Chief Eng	Chief Eng	Date	Section	n C	Chief Eng	QC Inspector
									rivi.
_									

NOTE: Date & initial all entries

Picklist Print Thursday, September 2	23 2010 3:01:41	PM										I	Page 1
Work Order ID: 6226		F IVI						,, ,,,	<u>. </u>			•	2
	0-639-011 Tungsten Carbide W	/earplate							tart Date: 9/24 Start Qty: 2.00		-	d Date: 9/27/20 e d Qty: 2.00	10
Comments:	PP D 02.09.	13 Re-format, A	dded M	S27130-S30	KJ								
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Sta Issued	tus
D2746 Wearshoe		Manufactured	No			105	Each	10.0000		2		L	
				Location		Loc	Qty	Loc Code					
				ST496A	46960		10 10			4690			
D2656-31 - Wearshoe		Manufactured	No		10500	105	Each	0.0000	1	, 2	203	d	,
D2656-13		Manufactured	No			105	Each	11.0000	1	2			
				<u>Location</u> FP020	57354	Loc	<u>Qty</u> 11 11	Loc Code	_	(730	5 4	,	
ALS7-1032-130 . Insert		Purchased	No			105	Each	1,868.000	36	72 .		6	[4]5/s z

Insert

Loc	<u>cation</u>	Loc Oty	Loc Code	
FP		851		
	115079	851		M1/507)
ST2	282	1017		
	113238	17		
	115502	500		
	115581	500		

W/O:			V	VORK ORDER CHANG	SES				
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									ļ
									,
Part No:PAR		PAR #:	Fault Ca	tegory:	NCR: Yes	No DQ	A:	Date: _	
Resolution:			Disposition: Q			QA: N/C Closed: Date:			
NCR:			WORK OR	DER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC		,	tion B	Verifi	cation	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	Sect	ion C	Chief Eng	QC Inspector
	٠.								
		·							
•									

Thursday, September 23, 2010 3:01:41 PM

Wôrk Order ID: 62264

D120-639-011

Parent Item:

D2648-3

Parent Item Name: Tungsten Carbide Wearplate



Start Date: 9/24/2010

Required Date: 9/27/2010

Start Qty: 2.00

Required Oty: 2.00



No

Manufactured


34.0000

Loc Code


10

)	Wearpad

_	MS27039-1-08	Purchased



Location



Each

105





	_
١	
ı	

Location	L	oc Oty	Loc Code	
ST291		1677		
110835		485		
114718	*	192	•	
115108		1000		
	105	Each	2 213 000	40





AN960JD10L		Purchased					
- Washer							





100154





MS27130-S30 Purchased

No

No

240.0000 Each



Location
ST293

Loc Oty 240 240

105

Loc Code

M/00/64

W/O:			W	ORK ORDER CHAN	NGES	-				
DATE STEP			DCEDURE CHANGE			Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
,									r Tour Wigi	
Part No	•	PAR #:	Fault Cat	egory:	NCR:	Yes N	lo DQA	:	Date:	
Reso		esolution:	Dispositi	QA: N	QA: N/C Closed: Date:					
NCR:			WORK ORI	DER NON-CONFOR	MANCE (NCR)				
DATE	STEP	Description of NC	Initial	Corrective Action S Action Description	Section B	Sign &	Verifica		Approval	Approval
		Section A	Chief Eng	Chief Eng	,	Date	Sectio	n C	Chief Eng	QC Inspector
	9 - 10 - 10 - 10 - 10 - 10 - 10 - 10 - 1									
						•				
r										
•	1 1									

NOTE: Date & initial all entries

REFERENCE ONLY ICA Page 19 (20 blank) of 20



32.2 WEIGHT AND BALANCE

The following weight and balance information is for the Dart wearplate kits that are being installed. The weight and balance of any wearplates that are being removed from the aircraft is the responsibility of the

	10/2:	LATERAL		LONGITUDINAL	
Installation	Weight	Arm	Moment	Arm	Moment
D120-639-011	3.1 lb	136.0 in	422 in lb	±40.7 in	±126 in lb
TUNGSTEN CARBIDE WEARPLATE KIT	1.4 kg	3.45 m	4.8 m kg	±1.04 m	±1.5 m kg
D120-639-013	4.1 lb	136.0 in	558 in lb	±40.7 in	±167 in lb
SURFACITE™ WEARPLATE KIT	1.8 kg	3.45 m	6.2 m kg	±1.04 m	±1.9 m kg

32.4 PARTS LIST

Qty	Qty	B. (Allowsham	Description
-011	-013	Part Number	
X.		D120-639-011	TUNGSTEN CARBIDE WEARPLATE KIT
	Х	D120-639-013	SURFACITE™ WEARPLATE KIT
71	1	D2746	WEARPLATE
1:	1	D2656-31	WEARPLATE
1	1	D2656-13	WEARPLATE
5		D2648-3 / *	WEARPAD
	5	D2648-7	WEARPAD
40	40	ALS7-1032-130	INSERT
Ì		or AKS7-1032-130	
		or ALS4-1032-130	
		or AKS4-1032-130	
40	40	MS27039-1-08	\$SCREW
40	40	AN960JD10L	WASHER



	DESIGN DRAWN BY			DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA		
ı	CHECKE	D _	APPROVED	DRAWING NO.	REV. A	
1	•	#	#	DSI 9223	SHEET 1 OF 1	
ı	DATE		<u> </u>	TITLE	SCALE	
	01.1	1.19		WEARPLATE INSERTS	NTS	
	Α		01.11.19	NEW ISSUE		

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS IIN-D120-639 Rev. A

> **REF. CANADIAN STC SH01-25** FAA STC: SR01347NY

REFERENCE


REPLACE (4) AFTMOST ALS7-1032-130 INSERTS WITH (4) RNS1032-330 / MS27130-S30 INSERTS. UPDATE PARTS LIST AS FOLLOWS:

REPLACE:

QTY -011	QTY -013	Part Number	Description
40	40	ALS7-1032-130	INSERT

WITH:

QTY -011	QTY -013	Part Number	Description	
36_	36	ALS7-1032-130	INSERT	
4	4 ;	RNS1032-330 or MS27130-S30	INSERT /	-



OF Ø0.297 FOR THESE 4 INSERTS

CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION **BRANCH** DAO # 01-O-01 D. SHEPHERD (DE # 02)

NOV 19, 2001 DATE: CERT. NO.: SH01-25 **ISSUE NO.:**